



Solutions for Improved Combustion Control

PROBLEM

- Unreliable burner lightoff
- Unable to meet current NFPA 86 Codes
- Poor burner efficiency causing increase utility cost
- Lack of burner temperature control resulting in poor temperature uniformity



SOLUTION

- ✓ Automated burner start-up and shut down
- ✓ Updated gas combustion skid to meet latest codes
- ✓ Fuel/ Air Ratio Control for optimum efficiency
- ✓ State of the art temperature and flame safety control in a single platform



CALL OR VISIT OUR NEW WEB SITE FOR THE PRODUCT SOLUTION TO MEET YOUR NEEDS

LOY-INSTRUMENT.COM

Cleveland Office
Phone: (216) 581-5448
cleveland@loy-instrument.com

Indianapolis Office
Phone: (317) 890-0474
indianapolis@loy-instrument.com

Fort Wayne Office
Phone: (260) 471-2171
fortwayne@loy-instrument.com